

KCC OIL/GAS REGULATORY OFFICES

Date: 05/16/14

District: 01

Case #: _____

- New Situation
- Response to Request
- Follow-Up

- Lease Inspection
- Complaint
- Field Report

Operator License No: 5144

API Well Number: 15-135-25,773-00-00

Op Name: Mull

Spot: NWNWNENW Sec 24 Twp 19 S Rng 23 E / W

Address 1: 1700 N Waterfront PKWY

105 (133) Feet from N / S Line of Section

Address 2: Bldg 1200

1535 (1503) Feet from E / W Line of Section

City: Wichita

GPS: Lat: 38.39224 Long: 99.81951 Date: 5/16/14

State: Kansas Zip Code: 67206 -

Lease Name: Erb Unit Well #: 1-24

Operator Phone #: (316) 264-6366

County: Ness

Reason for Investigation:

Witness Alt. II

Problem:

None

Persons Contacted:

Findings:

8-5/8"@218"W/165sxs
TD@4475'
5.5@4470"W/180sxs
Port Collar@1537"W/165sxs-SMD-2%cc-1/4#floseal-15sxs to pit.

Action/Recommendations:

Follow Up Required Yes No

Date: _____

None, Alt. II requirements have been met.

KCC WICHITA
MAY 27 2014
RECEIVED

Verification Sources:

Photos Taken: _____

- | | | |
|---------------------------------------|---|-------------------------------------|
| <input type="checkbox"/> RBDMS | <input type="checkbox"/> KGS | <input type="checkbox"/> TA Program |
| <input type="checkbox"/> T-I Database | <input type="checkbox"/> District Files | <input type="checkbox"/> Courthouse |
| <input type="checkbox"/> Other: _____ | | |

By: Michael J. Maier
Michael Maier

Retain 1 Copy District Office
Send 1 Copy to Conservation Division

MAY 21 2014

KCC DODGE CITY

Form: _____

Date: 05/16/14

District: 01

License #: 5144

Op Name: 5144

Spot: NWNWENW Sec 24 Twp 19 S Rng 23 E W

County: Ness

Lease Name: Erb Unit Well #: 1-24

I.D. Sign Yes No

Tank Battery Condition
Condition: Good Questionable Overflowing

Pits, Injection Site
Fluid Depth: _____ ft; Approx. Size: _____ ft. x _____ ft.

Oil Spill Evidence

Abandoned Well Potential Pollution Problem Yes No

Lease Cleanliness
 Very Good Satisfactory Poor Very Bad

Gas Venting Yes No

Pits
Fluid Depth: _____ ft; Approx. Size: _____ ft. x _____ ft.

Saltwater Pipelines
Leaks Visible: Y N Tested for Leaks: Y N

Flowing Holes

TA Wells

Monitoring Records

SWD/ER Injection Well Yes No Ness

Permit #: _____ Pressure - Actual: _____ psi; Authorized: _____ psi

Permit #: _____ Pressure - Actual: _____ psi; Authorized: _____ psi

Permit #: _____ Pressure - Actual: _____ psi; Authorized: _____ psi

Permit #: _____ Pressure - Actual: _____ psi; Authorized: _____ psi

Gauge Connections Yes No

Tubing: _____; T/C Annulus: _____; C/SP Annulus: _____

Tubing: _____; T/C Annulus: _____; C/SP Annulus: _____

Tubing: _____; T/C Annulus: _____; C/SP Annulus: _____

Tubing: _____; T/C Annulus: _____; C/SP Annulus: _____

API Number	Footages	Spot Location	GPS	Well #	Well Status
15-135-25,773-00-00	133FNL 1503FWL	NWNWENW	38.39224-99.81951	1-24	Cement circulate to surface