## KCC OIL/GAS REGULATORY OFFICES

Date: <u>06/11/14</u>	District: <u>01</u>	Case #:			
	New Situation	Lease Inspection			
	Response to Reques	t Complaint			
	Follow-Up	✓ Field Report			
Operator License No: 9408	API Well Number: 15-	101-22518-00-00			
Op Name: Trans Pacfic Oil Corporation	Spot: <u>N/2S/2SW</u>	Sec 11 Twp 17 S Rng 27 E / W			
Address 1: 100 S Main Ste 200	990 (1013)	Feet fromN / V S Line of Section			
Address 2:	1320 (1318)	Feet from E/VW Line of Section			
City: Wichita	GPS: Lat: <u>38.58438</u>	Long: 100.28001 Date: 6/11/14			
State: <u>Kansas</u> Zip Code: <u>67202</u> <u>-3735</u>	Lease Name: Hanks A	Well #: <u>_2-11</u>			
Operator Phone #: (316) 262-3596	County: Lane				
Reason for Investigation:					
Witness Alt.II					
Problem:					
None					
None					
Persons Contacted:					
	<del></del>				
Findings:					
8-5/8"@221'/150sxs	<del>-</del> -				
TD@4577'					
4-1/2"@4577'W/195sxs					
Port Collar@1932'W/175sxs-smd-1/4#floseal	-2%cc-15sxs to nit	i			
17 17 30114 (6 1002 17) 17 3080 31114 17 17 1100341	27000 100x0 to pit				
Action/Recommendations: Follow	Up Required Yes	No 🗗 Date:			
None, Alt.II requirements have been met.		KCC WICHITA			
		JUN 16 2014			
		JOM 19 5011			
		RECEIVED			
Verification Sources:	<del></del> -	Photos Taken:			
	A Program	Mula I Allan			
	Courthouse By:	may fuller			
Other:RECEIVED					
Retain I Copy District Office		$\cap$			
Retain I Copy District Office Send I Copy to Conservation Division 2014		Form:			
KCC DODGE OF TAKE		<u> </u>			
KCC DODGE CITY		<del>-</del>			

Date: <u>06/11/14</u>	_	District: <u>01</u>		License #: <u>9408</u>		
Op Name: <u>9408</u>		Spot: <u>N/2</u>	S/2SW	Sec <u>11</u> Twp <u>17</u>	S Rng <u>27</u> E 🕢 W	
County: Lane		Lease Nan	ne: <u>Hanks A</u>		Well#: <u>2-11</u>	
I.D. Sign Yes No		<u> </u>	Gas Venting [	Yes No		
Tank Battery Condition  Condition: Good Questiona	ble Overfloo	wing [5]	Pits Fluid Depth:	ft; Approx. Size	e:ft. xft.	
Pits, Injection Site Fluid Depth:ft; Approx.	Size:	ft. xft.	Saltwater F Leaks Visibl	_ =	ested for Leaks: Y N	
Oil Spill Evidence	oles					
Abandoned Well Potential Poll	ution Problem	Yes No 🖸	TA Wells			
Lease Cleanliness Very Good Satisfactory	Poor Ver	ry Bad	Monitoring	Records		
SWD/ER Injection Well Yes	-	Lane 🖸	-	tions Yes No	[K7]	
Permit #: Pressure – Actu					; C/SP Annulus:	
Permit #: psi; Authorized: psi			Tubing:; T/C Annulus:; C/SP Annulus:			
Permit #: Pressure - Actu Permit #: Pressure - Actu		thorized: psi thorized: psi		[ Tubing:		
		ps-				
API Footages	Spot Location	GPS Well #		Well Status		
1013FSL 15-101-22518-00-00 1318FWL	N/2S/2SW	38.58438-100.28011 2-11		Cement circulated to surface		
AMIONION,						
£2 - 1		<del> </del>				
( <u>) ( ) ( ) ( ) ( ) ( ) ( ) ( ) ( ) ( )</u>						
	,				<del></del>	
					<del></del>	

Retain 1 Copy District Office Send 1 Copy to Conservation Division

Form: \_\_\_\_