

District Plugging Report

Operator License No: <u>101</u>	String	Size	Depth	Pulled	Comments
Op Name: <u>KANSAS CORPORATION COMMISSION</u>	<u>SURF - Casing</u>	<u>8.000</u>			
Address 1: <u>226 N MAIN STE 220</u>	<u>PROD - Casing</u>	<u>4.000</u>			
Address 2: _____	_____	_____	_____	_____	_____
City: <u>WICHITA</u>	_____	_____	_____	_____	_____
State: <u>KS</u> Zip Code: <u>67202</u> - _____	_____	_____	_____	_____	_____

Proposed Plugging Report:

CLEAN OUT WELLS TO BOTTOM. PUMP FULL OF PORTLAND CEMENT, INSIDE AND OUTSIDE OF CASING. IF CEMENT IS PRESENT IN THE ANNULUS, CASING SHOULD BE PERFORATED IN AT LEAST 2 INTERVALS, UNLESS WELL IS DOCUMENTED AS ALT. 2 COMPLETION.

Actual Plugging Report:

Perfs:	Top	Bottom	Thru
--------	-----	--------	------

CLEARED AROUND THE WELL. PERFED AND WASHED TO 575'.
PUMPED 46 SACJS OF CEMENT. THE LOCATION WAS THEN
RESTORED.

[illegible]

Remarks	CONTRACT#38594;CONTROL#20140064-003;GPR BY TOM, TONY;IRREGULAR SECTION NAD83
---------	---

Plugged Due to Compliance Issue: ☐ Yes ☐ No**District: 03**

Received
KANSAS CORPORATION COMMISSION

SEP 04 2014

CONSERVATION DIVISION
WICHITA, KS

Thomas Belyea
(Technician)

Form: District Plugging Report –