## KCC OIL/GAS REGULATORY OFFICES

Date: 12/01/14	District: 01	Case #:					
	New Situation	Lease Inspection					
	Response to Request	Complaint					
	Follow-Up	✓ Field Report					
Operator License No: 4058	API Well Number: <u>15-145-21780-00-00</u>						
Op Name: American Warrior, Inc.	Spot: SENWNWSW	Sec <u>7</u> Twp <u>20</u> _S Rng <u>20</u> E / \sqrt{W}					
Address 1: 3118 Cummings Rd	2260 (2243)	Feet from N/ S Line of Section					
Address 2: P.O. Box 399	600(593)	Feet from E/W Line of Section					
City: Garden City	• •	Long: 99.58261 Date: 12/1/14					
State: Ks Zip Code: <u>67846</u> -		Well #: <u>2-7</u>					
Operator Phone #: (785) 398-2270	County: Pawnee						
Reason for Investigation:							
Witness Alt.II							
With 1655 Att. II							
Problem:							
None		-					
Payana Cantastadi							
Persons Contacted:	· · · · · · · · · · · · · · · · · · ·						
Findings:							
8.625@220'W/150sxs TD@4381'							
5.5@4381'W125sxs							
Port Collar@1401'W/125sxs-smd-1/4#flose	al-2%cc-15sxs to nit						
1 of condition 14/1/10000	ai 27000 100x0 to pit.						
		±i					
Action/Recommendations: Follo	ow Up Required Yes N	o 🖸 Date:					
None, Alt.II requirements have been met.							
	KCC WICH	HTA					
	DEC 19 20	<b>14</b>					
	_						
	RECEIVE	ED .					
Verification Sources:		Photos Taken:					
	TA Dragger	1 1 0211					
RBDMS KGS  T-I Database ✓ District Files	TA Program Courthouse By:	whall Ware					
Other:		chael Maler					
Retain 1 Copy District Office RECEIVED Send 1 Copy to Conservation Division							
DFC 17 2014 W		Form:					

KCC DODGE CITY

Date: <u>12/01/14</u>			01		cense #: <u>4058</u>		
Op Name: <u>4058</u>				Sec <u>7</u> Twp <u>2</u>	_		
County: Pawnee		Lease Nat	me: <u>SNS</u>		Well #: <u>2-7</u>	·	
I.D. Sign Yes No		<u> </u>	Gas Venting [	Yes No		<u>.</u>	
Tank Battery Condition  Condition: Good Question	nable Overflow	ring	Pits Fluid Depth:	ft; Approx. S	ize:ft. x	ft.	
Pits, Injection Site  Fluid Depth:ft; Approx. Size:ft. xf		t. xft.	Saltwater Pipelines  Leaks Visible: Y N Tested for Leaks: Y N				
Oil Spill Evidence			Flowing Ho	bles			
Abandoned Well Potential P	ollution Problem	Yes No 🗐	TA Wells				
Lease Cleanliness Very Good Satisfactory	Poor Ver	्र y Bad	Monitoring	Records			
SWD/ER Injection Well Yes	No	Pawnee 🖺	Gauge Connec	tions Yes No		(C)	
Permit #: Pressure - Ac	ctual: psi; Au	thorized: psi	Tubing:	; T/C Annulus: _	; C/SP Annulus	:	
Permit #: Pressure - Ad				; T/C Annulus: _			
Permit #: Pressure - Ao		thorized: psi		; T/C Annulus:			
Permit #:Pressure - A	ctual: psi; Au	thorized: psi	Tubing:	; T/C Annulus:	; C/SP Annulus	<u></u>	
API Number Footage	Spot Location	GPS	Well #		Well Status		
2243FSI 15-145-21780-00-00 593FWL		38.32647-99.58	261 2-7	Cement circulated to pit			
				<u>.</u>			
					-		
		Sar Ja					