

# KCC OIL/GAS REGULATORY OFFICES

Date: 11/24/14

District: 01

Case #: \_\_\_\_\_

- New Situation
- Response to Request
- Follow-Up

- Lease Inspection
- Complaint
- Field Report

Operator License No: 3842

API Well Number: 15-101-22541-00-00

Op Name: Larson Engineering, Inc. dba Larson Operating Company

Spot: SENEENW Sec 9 Twp 16 S Rng 28  E /  W

Address 1: 562 W State RD 4

595 (627) Feet from  N /  S Line of Section

Address 2: \_\_\_\_\_

2565 (2620) Feet from  E /  W Line of Section

City: Olimtz

GPS: Lat: 38.68271 Long: 100.42261 Date: 11/24/14

State: Kansas Zip Code: 67564 -8561

Lease Name: James' Children's Trust Well #: 1-9

Operator Phone #: (620) 653-7368

County: Lane

**Reason for Investigation:**

Witness Alt.II

**Problem:**

None

**Persons Contacted:**

\_\_\_\_\_

**Findings:**

8-5/8"@257"W165sxs  
TD@4500'  
5.5@4497"W/125sxs  
Port Collar@2011"W/190sxs-smd-1/4#flo seal--2%cc-15sxs to pit

**Action/Recommendations:**

Follow Up Required  Yes  No

Date: \_\_\_\_\_

None, Alt.II requirements have been met.

**KCC WICHITA**  
**DEC 19 2014**  
**RECEIVED**

**Verification Sources:**

<input type="checkbox"/> RBDMS	<input type="checkbox"/> KGS	<input type="checkbox"/> TA Program
<input type="checkbox"/> T-I Database	<input checked="" type="checkbox"/> District Files	<input type="checkbox"/> Courthouse
<input type="checkbox"/> Other: _____	<b>RECEIVED</b>	

Photos Taken: \_\_\_\_\_

By: Michael J. Mauer  
Michael Mauer

Retain 1 Copy District Office  
Send 1 Copy to Conservation Division

**KCC DODGE CITY**

Form: \_\_\_\_\_

Date: 11/24/14

District: 01

License #: 3842

Op Name: 3842

Spot: SENEENW Sec 9 Twp 16 S Rng 28  E  W

County: Lane

Lease Name: James' Children's Trust Well #: 1-9

I.D. Sign  Yes  No

Tank Battery Condition  
Condition:  Good  Questionable  Overflowing

Pits, Injection Site  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Oil Spill Evidence

Abandoned Well Potential Pollution Problem  Yes  No

Lease Cleanliness   
 Very Good  Satisfactory  Poor  Very Bad

SWD/ER Injection Well  Yes  No Lane

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Gas Venting  Yes  No

Pits  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Saltwater Pipelines   
Leaks Visible:  Y  N Tested for Leaks:  Y  N

Flowing Holes

TA Wells

Monitoring Records

Gauge Connections  Yes  No

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

API Number	Footages	Spot Location	GPS	Well #	Well Status
15-101-22541-00-00	627FNL 2620FWL	SENEENW	38.68271-100.42261	1-9	Cement circulated to surface