KCC OIL/GAS REGULATORY OFFICES

Date: <u>12/02/14</u>	District: <u>01</u>					
•	New Situation Lease Inspection					
	Response to Request Complaint					
	Follow-Up Field Report					
Operator License No: 32331	API Well Number: 15-135-25828-00-00					
Op Name: DK Operating Inc.	Spot: SWNESWNE Sec 2 Twp 20 S Rng 25 E /					
Address 1: 621 Benton St.	<u></u> —					
Address 2:						
City: Jetmore	GPS: Lat: <u>38.34390</u> Long: <u>100.05006</u> Date: <u>12/2/14</u>					
State: Kansas Zip Code: 67854 -						
Operator Phone #: <u>(620) 357-6152</u>	County: Ness					
Reason for Investigation:						
Witness Alt.II						
Problem:						
None						
Persons Contacted:						
Torsons Contacted.						
Findings:						
8-5/8"@283'W/175sxs TD@4458 5-1/2"@4457'W/125sxs Port Collar@1680'W/200sxs-smd-1/4#flo	seal-2%cc-20sxs to pit					
·						
Action/Recommendations:	Follow Up Required Yes No Date:					
None, Alt.II requirements have been met	t.					
	KCC WICHITA					
	DEC 9 9 2014					
	i de la companya de					
	RECEIVED					
Verification Sources:	Photos Taken:					
RBDMS KGS	TA Program Pur Mahan Mahan					
T-I Database	Courthouse By: Wichard Major					
	Michael Małer					
Retain 1 Copy District Office Send 1 Copy to Conservation Division 1 7 2014	Rorm:					
KCC DODGE CITY	2/					

Date: <u>12/02/14</u>		_	District	: 01	Lice	ense #: <u>32331</u>	
Op Name: <u>32331</u>			Spot: <u>S</u>	WNESWNE _	Sec <u>2</u> Twp <u>20</u>	S Rng <u>25</u> E 📝 W	
County: Ness Lease N			ame: <u>Hoss</u> Well #: <u>2-2</u>				
I.D. Sign Yes	No			Gas Venting	Yes No	<u></u>	
Tank Battery Condition Condition: Good Questionable Overflowing			ing	Pits Fluid Depth:	ft; Approx. Siz	e:ft. xft.	
Pits, Injection Site Fluid Depth:ft; Approx. Size:ft. xft.				Saltwater Pipelines Leaks Visible: Y N Tested for Leaks: Y N			
Oil Spill Evidence				Flowing Holes			
Abandoned Well	Potential Polli	ution Problem	Yes No 🔊	TA Wells Monitoring	Records		
Lease Cleanliness Very Good S	atisfactory [Poor Ver	y Bad		,		
SWD/ER Injection Well Permit #: P Permit #: P Permit #: P	ressure – Actuaressure – Actuaressur	al:psi; Aut al:psi; Aut al:psi; Aut		Tubing: Tubing: Tubing:	; T/C Annulus: ; T/C Annulus:	; C/SP Annulus: ; C/SP Annulus: ; C/SP Annulus: ; C/SP Annulus:	
API Number	Footages	Spot Location	GPS	Well#		Well Status	
15-135-25,828-00-00	1556FNL 1605FEL	SWNESWNE	38.34390-100.0	05006 2-2	Alt.II done, cemen	t circulated to pit	
			F. 2. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1.				
	_						
			,				
_						,	

Retain 1 Copy District Office Send 1 Copy to Conservation Division

Form: ______