KCC OIL/GAS REGULATORY OFFICES

Date: <u>01/02/15</u>	District: 01	Case #:				
	New Situation	Lease Inspection				
	Response to Request	Complaint				
	Follow-Up	Field Report				
Operator License No: 5259	API Well Number: 15-135-	25,827-00-00				
Op Name: Mai Oil Operations, Inc.	Spot: NWNWSENE	Sec 19 Twp 2 S Rng 22 E / W				
Address 1: 8411 Preston Rd Ste 800	_1490 (1465)	Feet from N/ S Line of Section				
Address 2:	1175 (1161)	Feet from E / W Line of Section				
City: Dallas	GPS: Lat: <u>38.30118</u> I	ong: <u>99.79150</u> Date: <u>1/2/15</u>				
State: <u>Texas</u> Zip Code: <u>75225</u> <u>-5520</u>	Lease Name: B&R Dechant Well #: 2					
Operator Phone #: (214) 219-8883	County: Ness					
Reason for Investigation:						
Witness Atl.II						
Problem:						
None, cement circulated to surface.						
Persons Contacted:	KCC WICHITA					
	JAN 26 2015					
Findings:	RECEIVED					
TD@4430' 5-1/2"@4426'/130sxs Port Collar@1472'/180sxs-smd-1/4# flo seal-	-2%cc-20sxs to pit.					
Action/Recommendations: Follow	v Up Required Yes No	Date:				
None, Alt.II requirements have been met.						
Verification Sources:		Photos Taken:				
	TA Program Courthouse Micha	el Marer				
1 10		Form:				
KCC DODGE CITY		V m ⁵				

Date: <u>01/02/15</u>		_	D	istrict:	01		Lic	ense #: <u>5259</u>	
Op Name: <u>5259</u>) Name: <u>5259</u> S			Spot: <u>NWNWSENE</u>		ENE	Sec <u>19</u> Twp <u>2</u>	S Rng <u>22</u>	E √ W
County: Ness			L	ease Nai	ne: <u>B8</u>	:: B&R Dechant Well #: 2			
I.D. Sign Yes	No			S	Gas V	enting [Yes No		S
Tank Battery Condition Condition: Good Questionable Overflowing			5	Pi		ft; Approx. Si	ze:ft. x	sft.	
Pits, Injection Site			 -		Sa	ıltwater Pi	ipelines		2 2
Fluid Depth:	_ft; Approx. S	Size:fi	t. x	ft.	\vdash			Tested for Leaks:	_ = -
Oil Spill Evidence					IFI	owing Hol	les		
Abandoned Well	Potential Polli	ution Problem [Yes	No 🗈	T	'A Wells			
					Monitoring Records				
Lease Cleanliness Very Good S	atisfactory	Poor Ver	y Bad	ξή.					
SWD/ER Injection Well	Yes	No	Ness	20	Gaug	e Connect	ions Yes No		N)
Permit #: Pr	ressure – Actu	al: psi; Au	thorized:	psi	Tubii	ıg:	; T/C Annulus:	; C/SP An	nulus:
Permit #: Pt	ressure – Actu	al: psi; Au	thorized:	psi	Tubii	ıg:	; T/C Annulus:	; C/SP An	nulus:
Permit #: Pr	ressure – Actu	al: psi; Au	thorized:	psi			; T/C Annulus:		
Permit #: Pr	ressure – Actu	al: psi; Au	thorized:	psi	Tubii	ıg:	; T/C Annulus:	; C/SP An	nulus:
API Number	Footages	Spot Location		GPS		Well#		Well Status	
15-135-25,827-00-00	1465FNL 1161FEL	NWNWSENE	38.30118	38.30118-99.79°		2	New well, Alt,II co	mpleted	
				_					
				·	_				
				_	_				

Retain 1 Copy District Office Send 1 Copy to Conservation Division

Form: _____