

KCC OIL/GAS REGULATORY OFFICES

Date: 01/05/15

District: 01

Case #: \_\_\_\_\_

- New Situation
- Response to Request
- Follow-Up

- Lease Inspection
- Complaint
- Field Report

Operator License No: 3842

API Well Number: 15-101-22552-00-00

Op Name: Larson Engineering, Inc. dba Larson Operating Company

Spot: SENENENW Sec 23 Twp 18 S Rng 29  E /  W

Address 1: 562 W State RD 4

385 (360) Feet from  N /  S Line of Section

Address 2: \_\_\_\_\_

2479 (2481) Feet from  E /  W Line of Section

City: Olmitz

GPS: Lat: 38.48112 Long: 100.49510 Date: 1/5/15

State: Kansas Zip Code: 67564 -8561

Lease Name: Marlin Unit Well #: 1-23

Operator Phone #: (620) 653-7368

County: Lane

Reason for Investigation:

Witness Alt.II

Problem:

None

Persons Contacted:

KCC WICHITA  
JAN 26 2015

Findings:

8-5/8"@253'W165sxs  
TD@4650'  
4.5@4645'W/145sxs  
Port Collar@2115'W/235sxs-smd-1/4#flo seal--2%cc-20sxs to pit

Action/Recommendations:

Follow Up Required  Yes  No

Date: \_\_\_\_\_

None, Alt.II requirements have been met.

Verification Sources:

- RBDMS
- T-I Database
- Other: \_\_\_\_\_
- KGS
- District Files
- TA Program
- Courthouse

Photos Taken: \_\_\_\_\_

By: Michael Maier  
Michael Maier

Retain 1 Copy District Office  
Send 1 Copy to Conservation Division

RECEIVED  
JAN 20 2015  
KCC DODGE CITY

Form: \_\_\_\_\_

Km5

Date: 01/05/15

District: 01

License #: 3842

Op Name: 3842

Spot: SENENENW Sec 23 Twp 18 S Rng 29  E  W

County: Lane

Lease Name: Marlin Unit Well #: 1-23

I.D. Sign  Yes  No

Tank Battery Condition  
Condition:  Good  Questionable  Overflowing

Pits, Injection Site  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Oil Spill Evidence

Abandoned Well Potential Pollution Problem  Yes  No

Lease Cleanliness   
 Very Good  Satisfactory  Poor  Very Bad

Gas Venting  Yes  No

Pits  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Saltwater Pipelines   
Leaks Visible:  Y  N Tested for Leaks:  Y  N

Flowing Holes

TA Wells

Monitoring Records

SWD/ER Injection Well  Yes  No Lane

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure - Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Gauge Connections  Yes  No

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

API Number	Footages	Spot Location	GPS	Well #	Well Status
15-101-22552-00-00	360FNL 2481FWL	SENEENENW	38.48112-100.49510	1-23	Cement circulated to surface