

KCC OIL/GAS REGULATORY OFFICES

Date: 01/15/15

District: 01

Case #: \_\_\_\_\_

- New Situation
- Response to Request
- Follow-Up

- Lease Inspection
- Complaint
- Field Report

Operator License No: 5259  
 Op Name: Mai Oil Operations, Inc.  
 Address 1: 8411 Preston Rd Ste 800  
 Address 2: \_\_\_\_\_  
 City: Dallas  
 State: Texas Zip Code: 75225 -5520  
 Operator Phone #: (214) 219-8883

API Well Number: 15-135-25,840-00-00  
 Spot: S/2SENE Sec 19 Twp 20 S Rng 22  E /  W  
 1065 (1148) Feet from  N /  S Line of Section  
 320 (329) Feet from  E /  W Line of Section  
 GPS: Lat: 38.30204 Long: 99.78861 Date: 1/15/15  
 Lease Name: B&R Dechant Well #: 3  
 County: Ness

Reason for Investigation:

Witness Atl. II

Problem:

None, cement circulated to surface.

Persons Contacted:

KCC WICHITA

JAN 26 2015

Findings:

8-5/8"@265/170sxs  
 TD@4409'  
 5-1/2"@4408'/130sxs  
 Port Collar@1423'/170sxs-smd-1/4# flo seal-2%cc-20sxs to pit.

RECEIVED

Action/Recommendations:

Follow Up Required  Yes  No

Date: \_\_\_\_\_

None, Alt. II requirements have been met.

Verification Sources:

Photos Taken: \_\_\_\_\_

- RBDMS
- T-I Database
- Other: \_\_\_\_\_
- KGS
- District Files
- TA Program
- Courthouse

By: Michael Maier  
 Michael Maier

Retain 1 Copy District Office  
 Send 1 Copy to Conservation Division

RECEIVED  
 JAN 20 2015  
 KCC DODGE CITY

Form: \_\_\_\_\_

KMS

Date: 01/15/15

District: 01

License #: 5259

Op Name: 5259

Spot: S/2SENE Sec 19 Twp 20 S Rng 22  E  W

County: Ness

Lease Name: B&R Dechant Well #: 3

I.D. Sign  Yes  No

Tank Battery Condition  
Condition:  Good  Questionable  Overflowing

Pits, Injection Site  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Oil Spill Evidence

Abandoned Well Potential Pollution Problem  Yes  No

Lease Cleanliness   
 Very Good  Satisfactory  Poor  Very Bad

Gas Venting  Yes  No

Pits  
Fluid Depth: \_\_\_\_\_ ft; Approx. Size: \_\_\_\_\_ ft. x \_\_\_\_\_ ft.

Saltwater Pipelines    
Leaks Visible:  Y  N Tested for Leaks:  Y  N

Flowing Holes

TA Wells

Monitoring Records

SWD/ER Injection Well  Yes  No Ness

Permit #: \_\_\_\_\_ Pressure – Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure – Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure – Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Permit #: \_\_\_\_\_ Pressure – Actual: \_\_\_\_\_ psi; Authorized: \_\_\_\_\_ psi

Gauge Connections  Yes  No

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

Tubing: \_\_\_\_\_; T/C Annulus: \_\_\_\_\_; C/SP Annulus: \_\_\_\_\_

API Number	Footages	Spot Location	GPS	Well #	Well Status
15-135-25,840-00-00	1148FNL 329FEL	S/2SENE	38.30204-99.78861	3	New well, Alt, II completed

Retain 1 Copy District Office  
Send 1 Copy to Conservation Division

Form: \_\_\_\_\_