

8

DISTRICT CONSERVATION AGENT'S REPORT

TO:

State Corporation Commission
Conservation Division
800 Bittling Building
Wichita, Kansas

FILE NO. 39----2

LOCATION NW--NW-- SE $\frac{1}{4}$

SEC. 7 TWP. 34 RGE. 2West

Dry Hole Yes.... Abandoned Oil Well _____ Abandoned Gas Well _____

I have today completed supervision of plugging of:

Well No. ONE... Lease L.F.STEWART.

Operator THE AKIN OIL CO. Address \$) National Bank Bldg. 406

Tulsa Okla.

Field Wild Cat County SUMNER.

Total Depth 4567... Feet.

(Describe briefly the manner in which the well was plugged)


Filled with heavy mud to bottom of Surface pipe or 125 Ft then

set bridge with 10 sacks cement ~~then~~ that filled to 85 Ft

then used 10 sacks cement and rock to tp of surface pipe

then welded a steel plate on top of surface pipe.

the surface pipe was cemented in and that was all the pipe that was used in well.



W. Y. Buffington
District Conservation Agent

Date Jan 8--46..

7 34 2W
39 2