

R

DISTRICT CONSERVATION AGENT'S REPORT

To

State Corporation Commission
Conservation Division
800 Bitting Building
Wichita, Kansas

File No. _____

Location _____

Sec. 36 Twp. 33 Rge. 39

I have today completed supervision of plugging of:

Well No. 2 Lease Hallock

Operator Mc Knabo & G Co. Address 105 W Adams st. Chicago Ill.

Field Hugoton County Stevens

Total Depth 2756 Feet.

(Describe briefly the manner in which the well was plugged)

Well cleaned out to 2575 ft. 5 1/2" O D casing set at 2531, which would be 44 ft. under the shoe joint cemented with 50 sacks of cement.

The cement set for 36 hours then the rotary tools were run to the top of the cement, which was 2165.

410 ft. cement in the well of which 44 ft. is under the pipe. Tools were taken down and the hole was left in this condition. The contractor that did this work was Thomas &

Sanders Drilling Co. Pampa, Texas.

R. J. Phillippe
District Conservation Agent

Date Aug 3, 1944

PLUGGING
FILE REC 36 33 39W
BOOK PAGE 129 LINE 9

