
KANSAS STATE CORPORATION COMMISSION

CONSERVATION DIVISION AGENT'S REPORT

TO: Jewel M. Ogden, Director 500 Insurance Building 212 North Market Wichita 2, Kansas



File No. County: Janton
Location: 1350 f NL 130 f WL Sec. 33 Twp. 34 Rge. 40 (E) (W) L
Name of Field: Total Depth: 4540
I have this date completed supervision of plugging of:
Lease Name: C-A- Manuel Well No. 1-33
Operator's Full Name: Kanilton Bus Some
Complete Address: Boll886, Miller Tiesan
Plugging Contractor:
Address: License No.
Oil Well Gas Well Input Well SWD Well D & A
Other well as hereafter indicated:
Was any delay in plugging operations caused by Conservation Division Agent? Yes No 2
If yes how long? Reason:
Operation Completed: Hour Day Day Month Year 1960
The above well was plugged as follows:
Hole with fether 2335 with and Google
cent spatted for 330 to 300 in Mindt 1600:
30 sur cent le 1515 to 1600: Multo 30-
Pert something strolly.
Signed:
Conservation Vivision Agent
Reviewed: Acus Burst
"Field Supervisor
Rémarks: DATE DICED
INV. No. 300