DISTRICT CONSERVATION AGENT'S REPORT

TO:

State Corporation Commission Conservation Division. 800 Bitting Building Wichita, Kansas



-			FILE NO. 41-25
			LOCATION & Sec.
			SEC. 21 TWP. 34 RGE. 33W
Dry Hole	Abandoned Oil Well Ab	andoned Gas Well	X
I have this	date completed supervision	of plugging of:	•
	Lease Bruns		<u> </u>
Operator GA	erican Gas Production Do. MicsoScawiceoSidoScapens	Address_Bar	tlesville, Oklahoma
Field	Hugoton	County	Seward
Total Depth	2760 Feet.		,
Plugging Cor	ntractor	Halliburton Cem	enting Co.
	ntractor's License No		
Address	Duncan, Oklahoma		
	(Describe briefly the ma	anner in which th	ne well was plugged)
و الرواية	75 sax cement by Hallibu	rton from 2270' t	o 2671' or T. D.
	Mud from 2270' to 725'.	25 sx cement fr	om 720' to 580'
·	Mud from 580' to 40'. 6	sax cement to 4	'. Cut pipe off 4'
	below ground level & wel	d on steel cap.	
	FIFE on sea		
	STATE CORPORATION COMMISSIO	<u>√</u> Di	Street Conservation Agent
LUGGIN		Dada	July 11, 1954
2 1 34	Wichite, Kappa	!	,

Wichite, Kansao

PAGE 41 UNE 25