

R

DISTRICT CONSERVATION AGENT'S REPORT

TO:

State Corporation Commission
Conservation Division
800 Bitting Building
Wichita, Kansas

FILE NO. _____

LOCATION NE-NE-SW

SEC. 30 TWP 34 RGE. 25W

Lost

~~Dry~~ Hole _____ Abandoned Oil well _____ Abandoned Gas Well _____

I have this date completed supervision of plugging of:

Well No. 1 Lease Davis CORRIGAN TOWER

Operator Delhi oil corp Address 823 Corrigan Tower Dallas Texas.

Field _____ County Clark

Total Depth 499' Feet.

Plugging Contractor Same. hole filled with.

Plugging Contractor's License No. Buldozer. (Bill Johnson)

Address Same. Co Foreman

(Describe briefly the manner in which the well was plugged)

Lost circulation at 480' hit underground cavity drilled to 499' pulled tools. hole caved. leaving hole 18' x 30' x 20' deep.

Skidded rig 100' West.

Lost 1 Cameron Blowout preventer in hole. Filled hole with clay and sand with Buldozer. Above ground level

M A Rice
District Conservation Agent

Date 8-23-53

PLUGGING
FILE SEC 30 T 34 R 25W
BOOK PAGE 125 LINE 9

RECEIVED
STATE CORPORATION COMMISSION
AUG 28 1953
CONSERVATION DIVISION
WICHITA, KANSAS