

KANSAS  
STATE CORPORATION COMMISSION

CONSERVATION DIVISION AGENT'S REPORT

TO:  
Jewel M. Ogden, Director  
500 Insurance Building  
212 North Market  
Wichita 2, Kansas

File No. \_\_\_\_\_ County: Chick  
Location: E/2 NE SE Sec. 25 Twp. 34 Rge. 32 (E) (W)   
Name of Field: \_\_\_\_\_ Total Depth: 5570

I have this date completed supervision of plugging of:

Lease Name: Randell Well No. 4  
Operator's Full Name: Falcon Seaboard Drilling Co.  
Complete Address: Tulsa Okla.  
Plugging Contractor: Heurden Drilling Co.  
Address: \_\_\_\_\_ License No. \_\_\_\_\_

Oil Well \_\_\_\_\_ Gas Well \_\_\_\_\_ Input Well \_\_\_\_\_ SWD Well \_\_\_\_\_ D & A

Other well as hereafter indicated: \_\_\_\_\_

Was any delay in plugging operations caused by Conservation Division Agent? Yes \_\_\_\_\_ No

If yes how long? \_\_\_\_\_ Reason: \_\_\_\_\_

Operation Completed: Hour 6pm Day 14 Month January Year 1961

The above well was plugged as follows:

2472' of intermediate casing - 193' of 13 3/8" casing - Hole  
was filled to 2400' with heavy mud - Cement plug  
set at 2400' - 30 sack cement spotted at 2400' - Mud  
to 500' - Cementing plug set at 500' - 20 sack cement  
spotted at 500' - Hole mudded to 35' - Cementing plug set 35'  
10 sack cement spotted from 35' to base of casing.

Signed: [Signature]  
Conservation Division Agent

Reviewed: J. Lewis Brock  
Field Supervisor

Remarks:

RECEIVED  
1-26-61  
JAN 26 DATE 2/6/61  
CONSERVATION DIVISION  
2587-4