

DISTRICT CONSERVATION AGENT'S REPORT

TO:

State Corporation Commission
Conservation Division
800 Bitting Building
Wichita, Kansas

FILE NO. 26---31----

LOCATION C.SW--NW--NW---

SEC. 10 TWP. 35 RGE. 2West..

Dry Hole yes. Abandoned Oil Well _____ Abandoned Gas Well _____

I have today completed supervision of plugging of:

Well No. Two. Lease SLENTZ...

Operator Champlin Refining Co. Address Enid Okla...

Field Wildcat. County Sumner..

Total Depth 4953.. Feet.

(Describe briefly the manner in which the well was plugged)

Dumped 14 sacks Cement in bottom of hole, then filled pipe
with Rotary mud. shot pipe off at 3311. Keep hole filled with mud
While pulling pipe. then set bridge and dumped 20 sacks Cement at
Bottom of Surface pipe or 959 ft the mudded to. top and capped with
10 sacks Cement

The pipe puller had to haul mud for the Texasas well west of Caldwell
as these pind had dried up....

RECEIVED
CORPORATION COMMISSION
7-25-52
JUL 25 1952

W. J. Buffington
District Conservation Agent

Date July. 14--52.....

PLUGGING
FILE SEC. 10 T. 35 R. 2W
BOOK PAGE 26 LINE 31