DISTRICT CONSERVATION AGENT'S REPORT

TO:

Dry Hole ...

Field

Total Depth

Operator Sidwell et al

Hugoton

2790

State Corporation Commission Conservation Division 800 Bitting Building Wichita, Kansas

Abandoned Oil Well

I have today completed supervision of plugging of:

Lease Snare

Feet.

N AGENT'S REPORT
FILE NO. 87-40
LOCATION CSE
SEC. 9 TWP.34SRGE. 39W
Abandoned Gas Well X
ng of:
202 W.K.H. Bldg., Wichita, Kansas
Morton
he well was plugged)

(Describe briefly the manner in which the well was plugged)

Address

Halliburton pumped a plug to the top of the $5\frac{1}{2}$ " liner at 2620'. Put in 37' of rock and calseal. Ran $5\frac{1}{2}$ " string of casing. The casing stopped at 2526' and was unable to get

County Morton

the $5\frac{1}{2}$ " any lower so cemented it there with 150 sacks of cement. Plug circulated on the $5\frac{1}{2}$ " before cementing and it circulated with water. After cement was in, either the bridge gave away or the 7" casing burst below 2526' allowing all the cement to go to the bottom of the hole cementing it completely solid. Halliburton ran temperature survey which showed the cement to be behind the $5\frac{1}{2}$ " string of casing to 1760'. McCullough Tool Company shot the $5\frac{1}{2}$ " off at 1710'. Pumped the hole full of mud. Did not pull any 7" casing or surface pipe. Welded top of 10" surface casing after it

was completely full o f mud.

Phillipse
District Conservation Agent

Date April 20, 1953

PLUGGING
FILE SEC 9 18 4 R 39 W
BOOK PAGE & ZLINE 40