



DISTRICT CONSERVATION AGENT'S REPORT

TO:

State Corporation Commission
Conservation Division
800 Bittling Building
Wichita, Kansas

FILE NO. 13-39

LOCATION NW-NW-NE-

SEC. 17 TWP. 30 RGE. 1 West.

Dry Hole Yes. Abandoned Oil Well _____ Abandoned Gas Well _____

I have today completed supervision of plugging of:

Well No. one Lease VOILS.

Operator Allinson & Hatfield. Address 715 Brown BLDG. WICHITA KANSAS...

Field _____ County SUMNER..

Total Depth 4025. Feet.

(Describe briefly the manner in which the well was plugged)

Hole was filled with heavy mud to 315 the set a seta plug and
bridge at 3 20 and used 15 sacks cemnet then refilled with heavy mud to 15f
of top then set bridge and use uses 10 sacks cemnet. filling to.
top od surface pipe. ther is 315 ft of 8 5/8 surface pipe cemneted in
hole....

RECEIVED
Conservation Div.

JUL 6 1950-6-50

STATE CORPORATION
COMMISSION
KANSAS
W. J. Buffington
District Conservation Agent

Date June 30--50...

PLUGGING
FILE SEC. 17 39 1W
BOOK PAGE 2 LINE 39