## DIST

DISTRICT CONSERVATION AGENT'S REPORT
O:
tate Corporation Commission onservation Division ll North Broadway ichita, Kansas FILE NO.
LOCATION 150'S & 150'W of Cente
SEC. 16 TWP. 32 RGE. 32W
ry Hole X Abandoned Oil Well Abandoned Gas Well
have this date completed supervision of plugging of:
ell No. 1 lease Lambert
perator Draper Motors Corp.  Address 2344 Woodward Ave.,  Royal Oak, Michigan  County Seward
otal Depth 2745 Feet.
lugging Contractor Gibson Machine & Tool Co.,
lugging Contractor's License No.
ddress  Box 1111 Borger, Texas  (Describe briefly the manner in which the well was plugged)  Filled hole with heavy mud to 570 feet. Set Halliburton
bridging plug at 570 feet. Plugged with cement from 570
feet to 416 feet with 50 sacks. Filled with mud from 416 feet
to 35 feet. Plugged with 10 sacks of cement from 35 feet to 4
feet below surface. Cut off 8 5/8" 4 feet under surface
and welded a steel plate on top.
UGGING  WEER VALUE DIVISION  Wichite, Rances  DATE  January 18, 1955