

R/

KANSAS
STATE CORPORATION COMMISSION

CONSERVATION DIVISION AGENT'S REPORT

TO:
Jewel M. Ogden, Director
500 Insurance Building
212 North Market
Wichita 2, Kansas

File No. _____ County: Stanton

Location: ESE 1/4 Sec. 30 Twp. 29 Rge. 42 (E) (W) X

Name of Field: W.C. Total Depth: 5565-

I have this date completed supervision of plugging of:

Lease Name: Birchfield Well No. 1

Operator's Full Name: P.O. Beason

Complete Address: 1709 Sulphur Springs Dallas Texas

Plugging Contractor: Wassinger Petroleum Co.

Address: 801 Durand Street Wichita Kansas License No. D.P.

Oil Well _____ Gas Well _____ Input Well _____ SWD Well _____ D & A X

Other well as hereafter indicated: _____

Was any delay in plugging operations caused by Conservation Division Agent? Yes _____ No X

If yes how long? _____ Reason: _____

Operation Completed: Hour 3 PM Day H Month 1 Year 58

The above well was plugged as follows:

8 3/8" S.P. 1446' P.W.C. hole filled with heavy
Mud to 700' set Plug Displacer 90' cement
through drill pipe. Mud to 35' set Plug
cement to base of collar.

Cement Provided by Halliburton Manufacturing Co.

Signed: M.P. Bivins
Conservation Division Agent

Reviewed: J. Lewis Brock
Field Supervisor

Remarks:

PLUGGING
FILE SEC. 30 T. 29 R. 42W
BOOK PAGE 10 LINE 20

RECEIVED
STATE CORPORATION COMMISSION
JAN 6 1959
CONSERVATION DIVISION
Wichita, Kansas