KANSAS STATE CORPORATION COMMISSION

CONSERVATION DIVISION AGENT'S REPORT

J. P. Roberts
Assitant Director
500 Insurance Building
212 North Market
Wichita 2, Kansas

INV. NO. _____

15-175-00177-00-01



Operator's Full Name Davidor &	Davidor, Inc.
Complete Address: 4515 N. Santa	E, Oklahoma City, Oklahoma 73/18
Lease Name Katie Lee	Well No. 1
Location NE NE	Sec. 12 Twp. 33 Rge. 34 (W) (W)
County Seward	Total Depth 6425
Abandoned Oil Well Gas Well	Input Well SWD Well D & A X
Other well as hereafter indicated	None
Plugging Contractor: MeAllister	Eng. & Well Service & Haliburton
Address: Box 1370, Liber	al, Kansas License No.
Operation Completed: Hour11:00	PMDay 13 Month 10 Year 1967
The Above well was plugged as fold	lows:
8 5/8" to 1650! cirulated w/	cement. 4 1/2" to 4308' cemented.
Mud 4308! to 700!	Spotted 35 sacks cement 700' to 525'
Mud 525' to 50!	Plug, Hulls & 15 sacks cement 50' to 0'
Haliburton Rump Truck.	Pulled 2200' of 4 1/2" casing.
	· · · · · · · · · · · · · · · · · · ·
	· . · · · · · · · · · · · · · · · · · ·
I hereby certify that the above we	ell was plugged as herein stated.
INVOICED	Signed: Floring Even
ATE 10/17/69	Well Plugging Supervisor