

DISTRICT CONSERVATION AGENT'S REPORT

TO:

State Corporation Commission  
Conservation Division  
800 Bitting Building  
Wichita, Kansas

FILE NO. 6-38

LOCATION SW

SEC. 34 TWP. 25 RGE. 5E

Dry Hole \_\_\_\_\_ Abandoned Oil Well Yes Abandoned Gas Well \_\_\_\_\_

I have today completed supervision of plugging of:

Well No. 8 Lease S.H.Hill


Operator Lawrence Matthews Address 123 N. Denver, Eldorado, Kans.

Field Eldorado County Butler

Total Depth 628 Feet.

(Describe briefly the manner in which the well was plugged)

- Corrosion bridge at 540'
- Set 3 sacks cement plug on rock bridge
- Mud to 200'
- Set 5 sacks cement plug on rock bridge
- Filled to 10'
- Set 2 sacks cement cap
- Filled to surface



P	INDEXING
FILE	34 25 5E
BOOK	PAGE 6 LINE 38

Roy Elliott by J. A. Loman  
District Conservation Agent

Date 9-25-41

S H HILL LEASE

WELL # 8. S W 1/4 Sec. 34 Twp. 25 Range 5 Butler Co Kansas.

Total Depth 628'

Top of Pay 585'

Bottom of pay 621'

Casing Record

6 5/8" Casing 570'

5 1/2" Liner 80'

INDEXING  
FIL 34 25 25 E  
500 6 NE 38

