KCC OIL/GAS REGULATORY OFFICES

	New Situation Lease Inspection			
	Response to Request Complaint			
	Follow-Up Field Report			
	ronow-op			
Operator License No: 33922	API Well Number: 15-135-25876-00-00			
Op Name: Mustang Energy Corporation	Spot: NE-SW-SW Sec 2 Twp 20 S Rng 22 E / W			
Address 1: P.O. Box 1121	Feet from N/\sqrt{S} Line of Section			
Address 2:	Feet from Feet f			
City: Hays	GPS: Lat: 38,34409 Long: 99.72844 Date: 7/24/15			
State: KS Zip Code: 67601	Lease Name: Antenen Well #: 1			
Operator Phone #: (785) 623-0533	County: Ness			
	County: Ness			
Reason for Investigation:	KCC WICHTA			
Company requested a state witness to the al	30 30 20am			
Problem:	RECEIVED			
	- IVED			
Alternate II cementing requirements have no	t been met.			
Persons Contacted:				
None.				
Findings:				
TD is 4500' 5 1/2" was set @ 4498' w/150 s	x cement on the primary cementing job. Company opened the			
port collar @ 1460'. Quality Oilwell Cementing pumped 200 sx 80/20 poz QMDC cement, circulating 15 sx				
to the pit. Closed the port collar.	ig pampod 200 ox corre por amino comoni, chedianing to ox			
to the plan elected the periodical				
	v Up Required Yes No 🗗 Date:			
Action/Recommendations: Follow None. Alternate II cementing requirements h	<u> </u>			
None. Alternate II cementing, requirements h	<u> </u>			
None. Alternate II cementing requirements h				
None. Alternate II cementing, requirements h	<u> </u>			
None. Alternate II cementing requirements h	nave been met.			
None. Alternate II cementing requirements h				
None. Alternate II cementing requirements I	Photos Taken: O			
None. Alternate II cementing requirements I Verification Sources: KGS T-I Database Verification Files	Photos Taken: O TA Program Courthouse By:			
Verification Sources: Verification Sources: RBDMS T-I Database Vother: On-site witness ECEIVED	Photos Taken: O			
None. Alternate II cementing requirements I	Photos Taken: O TA Program Courthouse By:			

Date: <u>07/24/15</u>	District: 1	<u>.</u>	License #: 33922
Op Name: 33922	Spot: <u>NE-SW</u>	'-SW	Sec <u>2</u> Twp <u>20</u> S Rng <u>22</u> E 🗸 W
County: Ness	Lease Name: 🛕	ntenen	Well #: 1
I.D. Sign Yes No	নি Gas	Venting	Yes No
Tank Battery Condition Condition: Good Questionable Overflowing		Pits id Depth:	ft; Approx. Size:ft. xft.
Pits, Injection Site		Saltwater Pi	pelines in in
Fluid Depth:ft; Approx. Size:ft. x		eaks Visible	
Oil Spill Evidence	$\longrightarrow \vdash$	Flowing Hol	es
On Spin Evidence		rioning 110r	
Abandoned Well Potential Pollution Problem Yes	No⑤	TA Wells	
		Monitoring l	Records
Lease Cleanliness Very Good Satisfactory Poor Very Bad	<u>a</u>	terountoning i	
SWD/ER Injection Well Yes No Ness	Gar	uge Connecti	ions Yes No
Permit #: Pressure - Actual: psi; Authorized: _	psi Tul	bing:	; T/C Annulus:; C/SP Annulus:
Permit #: Pressure - Actual: psi; Authorized: _			; T/C Annulus:; C/SP Annulus:
Permit #: psi; Authorized: psi; Authorized:			; T/C Annulus:; C/SP Annulus:
Permit #: Pressure - Actual: psi; Authorized:	psi Tul	bing:	; T/C Annulus:; C/SP Annulus:
API Footages Spot Location	GPS	Well #	Well Status
		i I	KCC WICHITA
			JUL 3 0 2015
			RECEIVED
1 1 1			

Form: