

DISTRICT CONSERVATION AGENT'S REPORT

TO:

State Corporation Commission
Conservation Division
800 Bitting Building
Wichita, Kansas

R
W

FILE NO. ✓

LOCATION W. NE

SEC. 30 TWP. 29 RGE. 10W

Dry Hole Rotary Abandoned Oil Well _____ Abandoned Gas Well _____

I have today completed supervision of plugging of:

Well No. 1 Lease Cirkel

Operator ✓ ~~_____~~ Address St Bend, Kans

Field Berwick, Spruill & Harms, Inc. County Kingman

Total Depth 4760 Feet.

(Describe briefly the manner in which the well was plugged)

The hole was filled with heavy mud
4760 ft to 500 ft cement 500 ft to 455 ft
15 slx. mud 455 ft to 10 ft cement into
base of casing 12 max. 505 ft of 5 3/4 pipe
cemented & left in the hole

A. W. Kerr
District Conservation Agent

MAY 9 - 1947

Date 5-7-47

PLUGGING
FILE SEC 30 T 29 R 10W
BOOK PAGE 102 LINE 9

X