

DISTRICT CONSERVATION AGENT'S REPORT

TO:

State Corporation Commission
Conservation Division
211 North Broadway
Wichita, Kansas

FILE NO. _____

LOCATION NW-SE-NW

SEC. 23 TWP. 25 RGE. 13 W

Dry Hole Abandoned Oil Well _____ Abandoned Gas Well _____

I have this date completed supervision of plugging of:

Well No. 2 Lease MC Landless

Operator Melch & Olson Eng. Inc Address 203 Rule Bldg. Wichita

Field _____ County Stafford

Total Depth 4225 Feet.

Plugging Contractor Melch & Olson Eng. Inc.

Plugging Contractor's License No. _____

Address 203 Rule Bldg. Wichita Kansas
(Describe Briefly the manner in which the well was plugged)

Surf Pipe 8" @ 252 C.W. 200 ft. Cement
Plugged with hole full of Shell mud
to 540 feet and 1/2 cu. yd. shells and Plug
and 20 cu. yd. Cement through Drill Pipe
and Shell mud to 335 feet and 1/2 cu. yd.
of shells and Plug and 10 cu. yd. Cement
to base of Casing

W. M. Brown
District Conservation Agent

Date Nov-15-1956
11-17-56
CONSERVATION DIVISION
Wichita, Kansas

PLUGGING
FILE SEC. 23 T. 25 R. 13 W
BOOK PAGE 117 LINE 25