STATE OF KANSAS

STATE CORPORATION COMMISSION

Give All Information Completely

Make Required Affidavit

Mail or Deliver Report to:

Conservation Division

State Corporation Commission

WELL PLUGGING RECORD

State Corporation Commission 800 Bitting Building Wichita, Kansas	Sta	fford	County	y. Sec. 8	_{Twp.} 25S Rge	(E).	<u>13</u> (W)	
NORTH	Location as "NE	CNW#SW#" o	r footage from	m lines NW N	W NW_			
≠ #1	Lease Name	Lease Owner Magnolia Petroleum Company Lease Name W. H. SHANK Well No. 1						
	Office Address_	Box 9	OO Dalla	as, Texas				
 -	Character of W	ell (completed a	as Oil, Gas or	r Dry Hole) _	Dry Hole	5-4-	10.55	
	Date well comp Application for	plugging filed	,	· -	-	5-4-	19 55	
 	Application for					5-6-	19 55	
	Plugging comme					5-4- 5-4-	19 55	
<u> </u>	Plugging comple Reason for aban				Dry I		₁₉ 55	
	Reason for aban	donnent of wen	or producing	g ioimadon				
	If a producing		•	-			19	
Locate well correctly on above Section Plat	Was permission menced?		the Conserva	ation Division	or its agents bei	ore plugging	was com-	
Name of Conservation Agent who s	upervised plugging of this	s well M. A	• Rives			1.55		
Producing formation None	D	epth to top	Bottom		Total Depth of	f Well 433	U_Feet	
Show depth and thickness of all wa	ter, oil and gas formation	S.						
OIL, GAS OR WATER RECO	ORDS					CASING RE	CORD	
FORMATION	CONTENT	FROM	TO	SIZE	PUT IN	PULLEO		
None				9 5/8"	3161	None)	
			<u> </u>		-			
		,						
	-				-			
Describe in detail the manne	- in which the well was r	lugged indicati	ng suboro tho	mud fluid mag	nlaced and the	mathad as ma	thoda wood	
in introducing it into the hole. If			_		-			
feet for each plu								
	T77 1.	2201 4- 27	0/	. set Vell	l à humban		·	
<u> </u>	Plug from 4 plug, 1/2 s					on:		
	from cmnt t	o 40' fill	ed w/mud	, 40 Hal	liburton pl	Lug		
	& 1/2 sx hu							
	Plugging un				Rives, Co	orp.		
	Comm. Distr	ict Pluggi	ng Super	visor.	· -			
· · · · · · · · · · · · · · · · · · ·	·					<u> </u>		
							,	
<u> </u>								
					_			
<u> </u>	·							
				<u> </u>		·		
			<u>.</u>			<u>'</u>		
			•					
Name of Plugging Contractor	(Hadditional Prime Drilling	description is necessified to the description of the description is necessified to the description of the description is necessified to the de	ssary, use BACE	of this sheet)				
Address	Wichita, Kansas							
STATE OF KANSAS	, COU	NTY OF	Barton		_, SS.	,		
R. C. Bra			employee of	owner) MXXXX	—, ss. Mekokoopeenok)	of the above	e-described	
well, being first duly sworn on oa	th, says: That I have kn							
above-described well as filed and	that the same are true ar	d correct. So l	nelp me God.	· /				
. 1		(Signature)		w	aer			
			Box 770	Great Be	end, Kansas	5		
C	pefore me this 27th	.1 e		Ma	(Address)	55		
Subscribed and Sworn to I	serore we this _ = 1 (41	day of_	DL.	4	, 19. **	, , , , , , , , , , , , , , , , , , , 	j	
1 "	1 -4-		your	reet	SX 1 0	wer	Parkitta	
My commission expires	1-14-57	04.7000.0	E2.10**	ئے ہو۔ مور ترک رائد	Tong in I Ty	(E Notar	, r uono.	
		24-7358-5 3-	53-20M		00	114.8810R		
	،		CINICS	, ,	1000 - 1000 5-70 - 1000	5		
		PLUY!	GING	3/ ONSE	TVATION ON	VISION		
	\$P\$	A SEC-	- I <u>ニー</u> 関金	2 1	chita, Kanss			
	' 50	OK PAGE-	/_UHE	<u>`</u> '				

W. H. SHANK #1 Drld Dry & Abnd 5-4-55

NW NW NW Sec. 8-25S-13W

Stafford County, Kansas

Elevation 1957' KB

Total Depth 4330' RTD

tı

Seevers Field

4-14-55 4-18-55 Location Staked L C Case & W B Simmons, MPCo Civil Engr. Rig Up Completed Prime Drilling Co., Wichita, Kansas 4-19-55 Spud Date 1:00 AM 5-2-55 Total Depth 43301 11 11 Ħ Commenced Abandonment

tt

5:00 AM

Transfer No. In: 2722

Completed Abandonment

Casing Record:

9 5/8" 25.4# .250" WT Armco Slip Jt Rge 3 7 Jts Put in 316' Left in 316'

9 5/8" csng set @ 316' w/325 sx cmnt circ. 4-19-55

FORMATION	FROM	TO	FORMATION	DEPIH	SUB-SEA	SOURCE
Surface Clay	0	. 20	Heebner	3511	- 1556	Samples
Sand	20	85	Lansing	3684	-1729	Maf
Sandy Shale	85	185	Basal Penn. Congl.	140174	-2059	11
Shale w/Lime & Red Rock	185	245	Vio l a	<u>4214</u>	-2159	11
Red Bed & Shells	245	317	Simpson Shale	կ2կ0	- 2285	11
Red Bed, Shale & Shells	317	460	Arbuckle	4296	-2341	11
Red Bed & Sand	460	950	Total Depth	4330		
Shale & Shells	950	1260	-			
Shale w/Lime streaks	1260	1500				
Shale & Lime	1500	1795	Heebner	3511	- 1556	Schlum.
Shale & Sandy Lime	1795	1890	Lansing	3682	-1727	11
Lime w/Shale breaks	1890	2005	Basal Penn. Cong.	4013	- 2058	Ħ
Lime	2005	2080	Kinderhook sh.	4071	-2116	11
Shale & Lime	2080	2310	Viola	4113	-2158	tř
Shale w/Lime streaks	2310	2365	Simpson sh.	<u> </u>	- 2288	Ħ
Shale & Lime	2365 3250	3250 3525	Arbuckle	4296	- 2341	11
Lime	3250	3525				
Lime & Shale	3525	3685				
Lime	3685	3750				
Shale & Lime	3750	3840	NO CODES DEDESTANTO	10 COTTE!	SEED LOID	TODO
Lime	3840	3910	NO CORES, PERFORATION		EZES, ACID	PORS
Lime & Shale	3910	3960	OR FRAC JOBS ON THIS	METIT		
Lime	3960	3995				
Cherty Lime	3995	4078 1.335	DI MAGTICA AND ADAMOND	COMO DOCA	א א א א א א	1
Lime, Chert & Shale	4078	4115	PLUGGING AND ABANDOM	TENT RECC	THU: P&A 5	-4-55
Lime & Shale	4115	4170 4200	TT A 1.0001 4- 27		34 TI_77	
Lime, Chert & Shale	7500 7500	4200 4225	Plug from 4330' to 31			
Lime Cherty Lime	4200	4240 4240	plug, 1/2 sx hulls 25			
Shale, Sand, Lime & Chert	7570	4285	from cmnt to 40° fill plug & 1/2 sx hulls &			
Lime & Shale	4285	4205	cellar. Plugging und			
Lime	4310	4310 4330	M. A. Rives, Corp. Co			
ROTARY TOTAL DEPTH	4)10	4330	Supervisor.	NIMI DTS	or TOO LTUBE	2miR
OIL STRING SET @		4.) D & A	Orbet ATOOL®			
PLUG BACK DEPTH		D & A				
A AND THE CALL THE TAX		- 0. A				

DRILL STEM TESTS:

No.	Date	From	_To_	Kind of Test	Tool @	Top Ck	Btm Ck	Time	Results
1	4-30-55	4026	4078						Steady blow thruout test,
				rec 40° drlg	-	="			
2	5 - 3 - 55	3886	3916	Straddle 3					Weak blow 20 mins, rec

DRILLING AND EXPLORATORY OPERATIONS PERFORMED:

4-19-55 Spudded, 1:00 AM; Set 9 5/8" csng @ 316' w/325 sx cmnt circ.


Top Heebner 3511; top Kansas City 3684!

4-30-55 D.S.T. #1

TD 4330; sun Schlumberger Electric Logs; wait on orders to abandon

D.S.T. #2

Plugged & Abandoned, 5:00 AM



IVED