

DISTRICT CONSERVATION AGENT'S REPORT

R

TO:

State Corporation Commission
Conservation Division
211 North Broadway
Wichita, Kansas

FILE NO. _____

LOCATION S41-S6W-NE

SEC. 17 TWP. 25 RGE. 14 W

Dry Hole Abandoned Oil Well _____ Abandoned Gas Well _____

I have this date completed supervision of plugging of:

Well No. 1 Lease Hall

Operator Alpine Oil & Royalty Co., Inc. Address 1100 Bittner Bldg. Wichita

Field _____ County Stafford

Total Depth 4470 Feet.

Plugging Contractor Quaker Drilling Co., Inc.

Plugging Contractor's License No. _____

Address 1100 Bittner Bldg. Wichita Kansas

(Describe briefly the manner in which the well was plugged)

Surf. Pipe 8 3/8 @ 2.54 c.w.c.
Plugged with hole full of Well mud
to 240 and 3/4 cu. of hullo and Plug and
90 lbs. of cement. Through riser pipe - and
Well mud and 3/4 cu. of hullo - Plug and
100 lbs. of cement. To base of collar

R.M. Brundage
District Conservation Agent

RECEIVED Date Nov-24-56

PLUGGING STATE CORPORATION COMMISSION

FILE SEC. 17 T. 25 R. 14W 2 : 1958 11-26-56

BOOK PAGE 119 LINE 16

COMMISSION