

DISTRICT CONSERVATION AGENT'S REPORT

TO:

State Corporation Commission  
Conservation Division  
211 North Broadway  
Wichita, Kansas

FILE NO. \_\_\_\_\_  
LOCATION 3N-3N-7E  
SEC. 7 TWP 24 RGE. 5W

Dry Hole  Abandoned Oil Well \_\_\_\_\_ Abandoned Gas Well \_\_\_\_\_

I have this date completed supervision of plugging of:

Well No. 1 Lease Mills  
Operator Halliburton Oil Producing Co Address Duncan Okla  
Field  County Reno

Total Depth 4044 Feet.

Plugging Contractor Sterling Drdg Co

Plugging Contractor's License No.

Address Sterling Kans  
(Describe Briefly the manner in which the well was plugged)

Grinded pits and circulated, hole made solid at 300', 2.5 ex cement. Then 9 jts drill pipe, mud to 15', bridge, 8 ex cement at top.

District Conservation Agent

Date 8-26-1957

PLUGGING  
FILE SEC 1 T 24 R 5W  
BOOK PAGE 40 LINE 19

8-27-57