


DISTRICT CONSERVATION AGENT'S REPORT



TO:

State Corporation Commission
Conservation Division
211 North Broadway
Wichita, Kansas

FILE NO. 1

LOCATION SE-SE-34W

SEC. 9 TWP 24 RGE. 10W

Dry Hole Abandoned Oil Well _____ Abandoned Gas Well _____

I have this date completed supervision of plugging of:

Well No. 1 Lease Waggoner Waggoner

Operator Conschutz Doby Co, Inc. Address Wichita, Kan. ^{709 Un. Natl. Bk. Bldg.}

Field _____ County Renov

Total Depth 4090 Feet.

Plugging Contractor Company Tools

Plugging Contractor's License No. ✓

Address _____

(Describe Briefly the manner in which the well was plugged)

Grinded pits and circulated, solid bridge
at approx. 210', 15 sv cement thru 7 joints
drill pipe, mud to 25', bridge, 5 sv
cement at top.

Paul Durkee
District Conservation Agent

Date 10-6-56

RECEIVED
STATE CORPORATION COMMISSION
10-8-56
OCT 8 1956
CONSERVATION DIVISION
Wichita, Kansas

PLUGGING
FILE SEC. 9 T. 24 R. 10W
BOOK PAGE 105 LINE 29