

DISTRICT CONSERVATION AGENT'S REPORT

TO:

State Corporation Commission
Conservation Division
211 North Broadway
Wichita, Kansas

FILE NO. ✓LOCATION SW-SW-4WSEC. 14 TWP. 35 RGE. 4WDry Hole ✓ Abandoned Oil Well _____ Abandoned Gas Well _____

I have this date completed supervision of plugging of:

Well No. 1 Lease Oil Mount 2740 East 14thOperator De Mier Oil Co. Inc. Address Tulsa Okla.Field ✓ County NowataTotal Depth 4055 Feet.Plugging Contractor Badger Drilling Inc.Plugging Contractor's License No. ✓Address Tulsa Okla.

(Describe briefly the manner in which the well was plugged)

Grassed pits and circulated, hole made
solid at 220', 2.5 cu cement thru 7
joints drill pipe. mud to 15' bridge,
8 cu cement at top.

RECEIVED
STATE CORPORATION COMMISSION

MAY 25 1956

CONSERVATION DIVISION
Wichita, Kansas

Paul D. Dinskey 5-25-56
District Conservation Agent

Date 5-24-56

PLUGGING			
FILE	SEC. <u>14</u>	T. <u>25</u>	R. <u>4W</u>
BOOK	PAGE <u>64</u>	LINE <u>43</u>	