

R

DISTRICT CONSERVATION AGENT'S REPORT

TO:

State Corporation Commission
Conservation Division
211 North Broadway
Wichita, Kansas

FILE NO. ✓

LOCATION NE-NE-SE

SEC. 5 TWP. 22 RGE. 5W

Dry Hole ✓ Abandoned Oil Well _____ Abandoned Gas Well _____

I have this date completed supervision of plugging of:

Well No. 1 Lease Rice 827 Beacon Bldg.

Operator Beardmore Drilling Co Address Wichita Kans

Field _____ County Reno

Total Depth 4061 Feet.

Plugging Contractor Company Tools

Plugging Contractor's License No. ✓

Address _____

(Describe briefly the manner in which the well was plugged)

Grouted pits and circulated, Hole
made solid at approx 170, 15 5/8
concrete thru 5 joints drill pipe.
Mud to 2.5, bridges, 5 5/8 cement
at top.

RECEIVED
STATE CORPORATION COMMISSION

MAR 16 1956

CONSERVATION DIVISION
Wichita, Kansas

[Signature]
District Conservation Agent

Date 3-15-56

3-16-56

PLUGGING
FILE SEC. 5 T 22 R 5W
BOOK PAGE 45 LINE 44