10

KCC OIL/GAS REGULATORY OFFICE

VO -		
15-891-2	ひみしみっ	00-00
(1) (C)	.00	

DATE 9/7/89	[] New Situation	- •
OPERATOR <u>Asher Associates Inc.</u> # 4868	[x] Response to Requ [] Follow-up	vest vest
NAME 5660 Greenwood Plaza Blvd., Suite 2	206LOCATION SW SE SW, SEC 20, T 26 S,R 29) L
ADDRESS Englewood, CO 80111	LEASE Monger Well # 4	
PHONE NO. OTHER	COUNTY Gray	_
REASON FOR INVESTIGATION: Witness Alternate I	I cementing.	Z,
	·	HCT I
	·	INSPECTION
PROBLEM: Need to complete Alternate II cemen	nting.	Į.
·	·	LEASE
PERSON(S) CONTACTED: Clint Base of Plains	Well Service	
FINDINGS: Pumped 2 sx gel,100 sx ATL, and 50) sx cement with 3% cc down tubing. Pumpe	ed
100 sx 60/40 Pozmix 6% gel 2% cc down backside.	Ran temperature log.	
Maximum pump pressure, tubing = 1200 psi, back	cside = 400 psi	COMPLAINT
Shut in pressure, tubing = 400 psi and backsid	le = 200 psi.	Com
Cemented by Allied.		<u> </u>
	procivad	
	STATE CONTROL TO COMMISSION	 -
	SEP : 9 1983	
·····	CONSELVATION DIVIDION	
· · · · · · · · · · · · · · · · · · ·	· · · · · · · · · · · · · · · · · · ·	
· · · · · · · · · · · · · · · · · · ·	photos taken:	→
ACTION/RECOMMENDATIONS: Ran temperature log on	9/8/89. Alternate II completed.	REPORT
Case closed.		
		FIELD
Retain 1 copy Joint District Office	By Michael R. Wilson	_ 💎
Send 1 copy Conservation Division	9/14/89	

LEASE INSPECTION

YES	NONE COMMENTS
[] I.D. Sign	[]
[] Tank Battery	[]; Condition: good [] questionable [] overflowing []
[] Pits, tank battery	[]; Fluid depthft.; approx. sizeft xft
[] Pit, injection site	[]; Fluid depthft.; approx. sizeft xft
[] Gas venting	
[] Oil spill evidence	[]
[] Saltwater evidence	[]; Surface flow; seepage
[] Saltwater pipelines	[]; Seepage visible Yes/No; tested for leaks Yes/No
[·] Flowing holes	
[] Abandoned wells	[]
[] TA wells	[]; Potential poll. prob; currently producing
[] SWD/ER Injection well [] SWD/ER Injection well [] SWD/ER Injection well [] SWD/ER Injection well	[]; Permit # Pressure-actual psi,Authorized psi []; Permit # Pressure-actual psi,Authorized psi
[] Monitoring records	
[] Gauge connections	[]: tubing ; T/C annulus ; C/SP annu
Water samples taken	oo sacistactory poor very bao
Reports prepared	