

DISTRICT CONSERVATION AGENT'S REPORT

TO:

State Corporation Commission
Conservation Division
211 North Broadway
Wichita, Kansas

FILE NO. ✓

LOCATION SE-SE-SE

SEC. 9 TWP 23 RGE. 7W

Dry Hole ✓ Abandoned Oil Well _____ Abandoned Gas Well _____

I have this date completed supervision of plugging of:

Well No. 1 Lease Wiegell

Operator Conschutz Dalg Co Inc Address Wichita Kans

Field ✓ County Ren

Total Depth 4075 Feet.

Plugging Contractor. Prime Dalg Co

Plugging Contractor's License No. _____

Address Wichita Kans

(Describe Briefly the manner in which the well was plugged)

Gunned pits and circulated, hole made solid at approx 180' 15 sy cement. Then drill pipe, mud to 25, bridge, 5 sy cement at top.

District Conservation Agent

Date 9-21-56

RECEIVED
STATE CORPORATION COMMISSION

PLUGGING
FILE SEC. 9 T. 23 R. 7W
BOOK PAGE 95 LINE 45

09-04-56
CONSERVATION DIVISION
Wichita, Kansas