

15-001-02946-00-00

KCC OIL/GAS REGULATORY OFFICES

Inspection Date 08/22/2016 District: 3 Incident Number: 5513

- New Situation Lease Inspection
- Response to Request Complaint
- Follow-up Field Report

Operator License No: 32709 API: 15-001-02946-00-00 Q3 SE Q2: SE Q1: NE
 Operator Name: Tim Splechter SEC 19 TWP 26 RGE 18 RGEDIR E
 Address: 1576 HWY 54 FSL: 2970
 City: Yates Center FEL: 165
 State KS Zip Code: 66783 Lease: Wadley Well No.: O-2
 Phone contact: 620-496-6100 County: AL

Reason for Investigation:

Try and locate a well on the operators license that was in a status of Inactive.

Problem:

No well at the location.

Persons contacted:

Tim Splechter, Operator

Findings:

I met with Tim Splechter, Operator of the Wadley lease, to try and locate a well that was on his inventory that had a status of Inactive. Mr. Splechter told me that he could not locate a well at the location that the well was suppose to be located. We went to the area where the well was suppose to be located. I used a metal detector and could not locate any area that a buried well might have been. The area is crop ground and a water way runs through the area the well was suppose to be located in. The area does not look like there had been a well drilled in that location.

Actions / Recommendation

Follow-up Required

Deadline Date:

Recommend that the well be changed from Inactive status and removed from Mr. Splechter inventory.

Photo's Taken: 0

- RBDMS KGS TA DBF Report Prepared By: Ryan M. Duling
- T1 DBF District Files Courthouse Position: E.C.R.S.