

INSPECTION REPORT

Case# _____

<input type="checkbox"/>	Complaint
<input type="checkbox"/>	New Situation
<input checked="" type="checkbox"/>	Response to request
<input type="checkbox"/>	Follow-up

Date of Inspection: January 19, 2016

Operator: Val Energy Inc.

License: 5822

Address: 125 N Market St. Ste. 1710

Location: NW/4 Sec. 21-8-35W

City/St: Wichita Kansas 67202

Lease: Otto

Phone: (316)-263-6688

County: Thomas

Reason for investigation: Response to request.

Problem: Report current status of well.

Findings:

- On the above reported data an inspection was conducted on the Otto lease. The inspection revealed the following observations:
- The tank battery that serves the Otto lease is located NW-NE-NW/4 of section 21-8-35W.
- The Otto # 1-21 located SW-SW-NE-NW/4 is an active oil well. The Gps location is -101.23616W & 39.34929N. The API # is 15-193-20,938. The well was spudded on November 20, 2014.
- The drilling pits have been closed.

Photos: No

Action /recommendations:

- No action required.

Darrel Dipman ECRS
(agent)

Darrel Dipman
(signature)

cc: file

KCC
FEB 11 2016
HAYS, KS