

INSPECTION REPORT

15-193-20928-00-00

Case# _____

<input type="checkbox"/>	Complaint
<input type="checkbox"/>	New Situation
<input checked="" type="checkbox"/>	Response to request
<input type="checkbox"/>	Follow-up

Date of Inspection: January 19, 2016

Operator: Val Energy Inc.

License: 5822

Address: 125 N Market St. Ste. 1710

Location: SW/4 Sec. 1-8-36W

City/St: Wichita Kansas 67202

Lease: STA LLC # 1

Phone: (316)-263-6688

County: Thomas

Reason for investigation: Response to request.

Problem: Report current status of well.

Findings:

- On the above reported data an inspection was conducted on the STA LLC lease. The inspection revealed the following observations:
- The tank battery that serves the STA LLC lease is located NW-NW-SW/4 of section 01-08-36W.
- The STA LLC # 1, located SE-SE-NW-SW/4 is an active oil well. The GPS location is -101.29266W & 39.38567N. The API # is 15-193-20,928. The well was spudded on September 27, 2014.

Photos: No

Action /recommendations:

- No violations were observed during the lease inspection or subsequent research.

Darrel Dipman ECRS
(agent)

Darrel Dipman
(signature)

cc: file

KCC
FEB 11 2016
HAYS, KS