

15. 167. 00 137. 00. 00

R

DISTRICT CONSERVATION AGENT'S REPORT

TO:

State Corporation Commission
Conservation Division
211 North Broadway
Wichita, Kansas

FILE NO. _____

LOCATION NW-NW-SW

SEC. 22 TWP. 12 RGE. 15W

Dry Hole ~~_____~~ Abandoned Oil Well _____ Abandoned Gas Well _____

I have this date completed supervision of plugging of:

Well No. 1 Lease Schmeidler

1411 Mile High Center

Operator Anschutz Drilling Co. Inc. Address 709 Union Nat'l. Bldg. Wichita, Kansas.

Denver, Colo.

Field _____ County Russell

Total Depth 3203' Feet.

Plugging Contractor Anschutz Drilling Co. Inc.

Plugging Contractor's License No. _____

Address 709 Union Nat'l. Bldg. Wichita, Kansas.

(Describe briefly the manner in which the well was plugged)

Surface Pipe 8 5/8" @ 190' c.w.c. 150 sx.

Fill hole with heavy mud to 180' from top, 1/2 sx. hulls, Halliburton

plug and 20 sx. cem. through drill pipe. Then mud to 40' from top,

1/2 sx. hulls, Halliburton plug and 10 sx. cem. to base of cellar.

RECEIVED
COMMISSION

FEB 20 1956

Milton Schmeidler
District Conservation Agent

Date 7-17-56

PLUGGING
FILE SEC. 22 TWP. 12 R. 15W
BOOK MC239 LINE 38

CONSERVATION DIVISION
Wichita, Kansas