

R

DISTRICT CONSERVATION AGENT'S REPORT

TO:

State Corporation Commission
Conservation Division
800 Bitting Building
Wichita, Kansas

FILE NO. _____

LOCATION SF-SE-SW

SEC. 23 TWP. 16 RGE. 11-1/2

Dry Hole X Abandoned Oil Well _____ Abandoned Gas Well _____

I have today completed supervision of plugging of:

Well No. 1 Lease Disque

Operator Merby Drilling Co Address Merby Bldg - Wichita - Kans.

Field _____ County Barton

Total Depth 3440 Feet.

(Describe briefly the manner in which the well was plugged)

Surface Pipe 8 3/8 - 183 ft. Circulated with cement.
1/2 full of heavy mud. Set Plug & 15 sacks
of cement at 183 ft. Through the Drill Pipe.
Mud to 30 ft. Plug & 10 sacks of cement
at the surface

C. M. Stouch
District Conservation Agent

Date 12-2-49

DEC 5 - 1949
12-5-49
STATE CORPORATION
COMMISSION
KANSAS

PLUGGING
FILE SEC 23-T-16R-11
BOOK PAGE 108 LINE 15