

15-001-28036-00-00

KCC OIL/GAS REGULATORY OFFICES

Inspection Date 03/15/2016 District: 3 Incident Number: 5451

- New Situation Lease Inspection
- Response to Request Complaint
- Follow-up Field Report

Operator License No: 34919 API: 15-001-28036-00-00 Q3 NW Q2: SE Q1: NE
 Operator Name: Nataraja Oil Corporation SEC 31 TWP 26 RGE 18 RGEDIR E
 Address: 601 North Kansas FSL: 3417
 City: Chanute FEL: 697
 State KS Zip Code: 66720 Lease: Wiles Well No.: 21
 Phone contact: 620-778-0738 County: AL

Reason for Investigation:

Operator filed a TA for a surface casing only well. Operator believes it is plugged.

Problem:

Well is on operator license as an inactive well.

Persons contacted:

Clarence Lyons, pumper, 620-778-0738

Findings:

I met with Clarence Lyons, pumper, to determine if well #21 was plugged or not. We ran a line down the well and hit solid at 2' down from surface. Mr. Lyons said he would get a backhoe and dig down and cut off casing to see if we could find cement. Operator dug down to approx 6" and encountered bedrock. Operator cut the 8" casing off. Cement was present. This well appears to have been plugged sometime years ago and no plugging report had ever been done. Operator filled hole back in and leveled around well site.

Actions / Recommendation

Follow-up Required

Deadline Date:

Well needs to be placed in PA status. Well appears to be plugged.

Photo's Taken:

0

- RBDMS KGS TA DBF T1-DBF
 - District Files Courthouse
- Report Prepared By: Ryan M. Duling Position: E.C.R.S.