

INSPECTION REPORT

Case# _____

<input type="checkbox"/>	Complaint
<input checked="" type="checkbox"/>	New Situation
<input type="checkbox"/>	Response to request
<input type="checkbox"/>	Follow-up

15-167-06193-00-00

Date of
Inspection: 09-22-2016

Operator: Manuel Corporation (Berexco, Inc)

License: 5363

Address: 2020 N. Bramblewood

Location: SE SW NW 32-11s-15w

City/St: Wichita, KS 67206

Lease: Dodge #5 15-167-06193

Phone: _____

County: Russell

Reason for investigation: Well was listed as abandoned under an expired license in RBDMS.

Problem: Well drilled in 1926. No plugging report associated with well. Circular depression at well location.

Findings:


- 9 a.m. Backhoe on location. Hit cable, wood, collars, and rocks from 5 feet below surface to approximately 14 feet. Faint discoloration of old hole observed. Nothing definite. Decided to get a track hoe to get deeper. Track hoe (Flatlander out of Hays) arrived 3 pm. Continued to dig. More cable, iron, and rock. At approximately 20 feet hit sand. Dug to 23 feet in sand. Limit of track hoe. No indication of old hole at that point. Decided not to excavate any further.

Photos: 3

Action /recommendations:

➤

Case Morris, District Supervisor
(agent)



(signature)

cc: file

Date: September 22, 2016

Manuel Corporation
Dodge #5
SE SW NW 32-T11s-R15w
Russell County, Kansas

Attempt to locate borehole of well drilled in 1926 with no casing and no record of plugging.



double-click in this frame to open up this Preview in a

DERBY, STEARNS & STREETER #5 DODGE

32-11-15W

SE SW NW

Contr. _____ RUSSELL County

E 1802 Comm 9-23-26 Comp 1-11-27 IP _____ D & A

Tops	Depth	Datum	Casing
LANS	2883	-1081	
TD	3004	-1202	

INDEPENDENT OIL & GAS SERVICE
WICHITA, K 67240

