

15-~~40246~~ 40246-00-00
013

KCC OIL/GAS REGULATORY OFFICES

Date: 09/28/16

District: 02

Case #: _____

- New Situation
- Response to Request
- Follow-Up

- Lease Inspection
- Complaint
- Field Report

Operator License No: 5394

API Well Number: 15-015-40246-00-00

Op Name: R.R. ABDERHALDEN

Spot: NW NE SW SW Sec 10 Twp 27 S Rng 4 E / W

Address 1: 100 S. MAIN

1070 Feet from N / S Line of Section

Address 2: STE 510

4417 Feet from E / W Line of Section

City: WICHITA

GPS: Lat: 37.71138 Long: 96.98669 Date: 9/28/16

State: KS Zip Code: 67202

Lease Name: BATES Well #: 6

Operator Phone #: (316) 262-3411

County: Butler

Reason for Investigation:

TA / COMPLIANCE

Problem:

Persons Contacted:

DWAIN STOUT

Findings:

DAVID BOLLENBOCK LOCATED CASING WITH METAL DETECTOR. RRA DUG WELL OUT & LOCATED 8" CASING ORANGE PEELED TO 12" CSG. CEMENT @ SURFACE IN 8" CASING, & THERE IS CEMENT ON BACKSIE OF 12". WELL IS PLUGGED.

Action/Recommendations:

Follow Up Required Yes No

Date: _____

CHANGE WELL STATUS TO PLUGGED

Verification Sources:

Photos Taken: YES

- RBDMS
- T-I Database
- Other: LEASE INSPECTION
- KGS
- District Files
- TA Program
- Courthouse

By: DUANE KRUEGER

Retain 1 Copy District Office
Send 1 Copy to Conservation Division

Form: 09/28/2016