

R

DISTRICT CONSERVATION AGENT'S REPORT

TO:

State Corporation Commission
Conservation Division
211 North Broadway
Wichita, Kansas

FILE NO. _____

LOCATION NE-NE-NW

SEC 23 TWP. 22 RGE. 15 W

Dry Hole Abandoned Oil Well _____ Abandoned Gas Well _____

I have this date completed supervision of plugging of:

Well No. 1 Lease Hirsch

Operator Transit Corporation Address 1516 Liberty Bk. Bldg. Okla. City Okla.

Field _____ County Pawnee

Total Depth 4023 Feet.

Plugging Contractor Transit Corporation

Plugging Contractor's License No. _____

Address 1516 Liberty Bk. Bldg. Okla. City Okla.

(Describe briefly the manner in which the well was plugged)

Surface pipe 8 7/8" @ 218' CWC. Filled hole with heavy mud. Pumped plug and 100 58 cem. Filling hole and surface pipe from 300' to base of cellar with cement. Pumping by Halliburton Cem. Co.

Warren H. Horner
District Conservation Agent

Date May 14 1955

PLUGGING
FILE SEC 23 TWP. 22 R. 15 W
BOOK PAGE 119 LINE 9

RECEIVED
STATE CORPORATION COMMISSION

MAY 17 1955 5-17-55

CONSERVATION DIVISION
Wichita, Kansas