KCC OIL/GAS REGULATORY OFFICES

Inspection Da	ate 01/12/2017	District:	3	Incident Number:					561	7
		☐ New Situation		☐ Lease						
		Response to R	equest	Comp	plaint					
		☐ Follow-up		_ ∀ Field	Report					
Operator Lice	nse No: 35171	•	4 ~ 4		•		NF C)2: SE	Q1: S\	Λ/
•	e: Iantha Reso	API:	SEC	07-20588-4 3 TW I						••
-	517 NW 1650 Ro		SEC	3 TW	- 23	RG	E 19 FSL:	KGE	DIR E 93	Ω
City: Garr		••					FEL:		205	
State KS	Zip Code: 6	6032 Le	ase:	Minckley		Wel	l No.:	R-16	200	<i>,</i> 0
Phone contac			uo	, , in local of	Co	บnty:		11.10		
Reason for Inv				_						
	-	well #R-16 (15-003	<u> </u>	-00-001 wa	s avar	drillad				
·	Thiyers to mid if	Well #14-10 (10-000	-20000) a	3 GVCI I	umeu	-			
Problem:										
Well listed as "	PW."									
Persons cont	acted:									
None.										
<u>Findings:</u>										
A field inspection	on on January 1	2, 2017 found well #	₽R-16 to	be an acti	ve prod	ducer.	On Fe	bruary 2	2, 2007,	
		ed a location on GP corded as an injection				itches	the we	ell location	on tor R-	
TO III TABBATO.	THE WEIL WEB. CO.	orded do arr injectiv	JI 11011	at that time	••					
	•									
Actions / Reco	mmendation	Follow-up R	<u>equire</u>	₫ 🗆	<u>Dea</u>	dline	Date:			
Update well loc	ation information	in RBDMS.								
					Photo	's Tal	ken:		0	
RBDMS	✓ KGS	☐ TA DBF	Report	Prepared	By: L	<u>evi S</u>	<u>hort</u>			
T1 DBF	☑ District File:	s ☐ Courthouse	Po	osition:	<u>ECRS</u>					
	•									