KCC OIL/GAS REGULATORY OFFICES

Inspection Da	ate 01/26/2017	District: 3		Incident Number:			5638	
		✓ New Situat	ion	☐ Lease Inspection				
		☐ Response	to Request	☐ Comple	aint			
		☐ Follow-up		☐ Field R	leport			
Operator Lice	nse No: 34998	API:			Q3	Q2:	Q1: SE	
Operator Nam	e: Ace Energy	LLc	SEC	1 TWP	31 RGE	21 RGE	DIR e	
Address: 117	'04 Aberdeen R	d		,	F	SL:	1724	
City: Leav						EL:	135	
State Ks	Zip Code: 6		Lease: F	Peggy Kruge		•	85	
Phone contact		-8602			County:	Cr		
Reason for Inv	<u>vestigation:</u>							
TA / Plugging								
	-							
Problem:								
Well location / s	status							
Persons cont	acted:							
Jonathan Freid	den, Casey Jess	eph, Dennis St	nuitz					
<u>Findings:</u>								
	mployees locate							
	agreed upon tha ugged. A previor						cate	
that there is an	other well at this	location but no	ne have be	en found. Th			d be	
updated to corr	ect intent #L 88	(15-037-01526) as not bein	ig drilled.				
						•		
Actions / Reco	mmondation	Eallow :	up Required	. □	Doodling D	ato:		
			up Keguirec	1 —	<u>Deadline D</u>	ate:		
i wiii reter this r	report to correct	tne issue.						
							_	
_		_			Photo's Take		0	
☑ RBDMS	✓ KGS	☐ TA DBF	Report	Prepared E	By: <u>Russell l</u>	<u>Hine</u>		
☐ T1 DBF	☑ District File	s 🗆 Courth	ouse Po	osition: <u>[</u>	E.C.R.S.			