

*R*

DISTRICT CONSERVATION AGENT'S REPORT

TO:

State Corporation Commission  
Conservation Division  
211 North Broadway  
Wichita, Kansas

FILE NO. \_\_\_\_\_

LOCATION NW-NW-NE

SEC. 28 TWP. 22 RGE. 11W

Dry Hole ✓ Abandoned Oil Well \_\_\_\_\_ Abandoned Gas Well \_\_\_\_\_

I have this date completed supervision of plugging of:

Well No. 2 Lease Curtis

Operator Ruschutz Holz Co. Inc. Address 709 W. North Br. Bldg. <sup>KANS.</sup> Wichita

Field \_\_\_\_\_ County Stafford

Total Depth 3685 Feet.

Plugging Contractor Ruschutz Holz Co. Inc.

Plugging Contractor's License No. \_\_\_\_\_

Address 709 W. North Br. Bldg. Wichita KANS.  
(Describe briefly the manner in which the well was plugged)

*Surf Pipe 8" @ 253 c.w.c.  
Plugged with hole full of fell mud  
to 240 feet and 3/4 hells & grad  
Plug and 20 sq cent. Through  
drill pipe and fell mud to 35 feet  
and 3/4 hells and 10 sq cent.  
to base of cellar*

RECEIVED  
STATE CORPORATION COMMISSION

*R. M. Brundage*  
District Conservation Agent

Date May - 24 - 56

PLUGGING  
FILE SEC. 28 T. 22 R. 11W  
BOOK PAGE 65 LINE 19

5-26-56