

## DISTRICT CONSERVATION AGENT'S REPORT

TO:





wichita, Kansas			
		FILE NO.	
		LOCATION NE. NE. SE	
•		SEC. 2 TWP. 22 RGE. 14-w	
Dry Hole A	bandoned Oil Well	Abandoned Gas Well	
I have today compl	eted supervision of	plugging of:	
Well No. 6	Lease	Wetiq	
Operation Ly	andard Oil Cold	dress 7009 Control Bldg Michila	-/1
		unty <u>Taffard</u>	
Total Depth 38	,	77	
(Describe br	iefly the manner in	which the well was plugged)	
^ ^		Circulated with coment:	
//	6 · // /	and Set Plua &	•
1 /	$\nu$	t sook the cough the	
		30St-Plub &	
		at The Rueloce-	
20 Octesta	T cenan	101 The standard	•
<del></del>	/ 		
***************************************			
		TATE CORPORATION COMMISSION	
		NOV 2 0 1952 11 - 20 -5	2
		CONSERVATION DIVISION	
PLUGGIN	6	(Cichila Kansasud) -	
9EC 2 122	14:34	District Conservation Agent	
TARE 6011	42	Date	