

KCC OIL/GAS REGULATORY OFFICES

Inspection Date 01/26/2017 District: 3 Incident Number: 5638

- Checked: New Situation, Response to Request, Follow-up; Unchecked: Lease Inspection, Complaint, Field Report

Operator License No: 34998 API: 15-037-01527-00-03 Q2: Q1: SE
Operator Name: Ace Energy LLC SEC 1 TWP 31 RGE 21 RGEDIR e
Address: 11704 Aberdeen Rd FSL: 1724
City: Leawood FEL: 135
State Ks Zip Code: 66211 Lease: Peggy Kruger Well No.: L88,L85
Phone contact: 773-209-8602 County: Cr

Reason for Investigation:

TA / Plugging

Problem:

Well location / status

Persons contacted:

Jonathan Freiden, Casey Jesseph, Dennis Shultz

Findings:

Ace Energy's employees located an abandoned well at this location. After researching available records it was agreed upon that this well was the Peggy Kruger # L 85 (15-037-01527). On 10/25/2017 the well was plugged. A previous operator had this well listed as L 88. RBDMS records now indicate that there is another well at this location but none have been found. The entry on RBDMS should be updated to correct intent #L 88 (15-037-01526) as not being drilled.

Actions / Recommendation

Follow-up Required [ ]

Deadline Date:

I will refer this report to correct the issue.

Photo's Taken: 0

- Checked: RBDMS, KGS, District Files; Unchecked: TA DBF, T1 DBF, Courthouse; Report Prepared By: Russell Hine; Position: E.C.R.S.