

R

DISTRICT CONSERVATION AGENT'S REPORT

TO:

State Corporation Commission
Conservation Division
211 North Broadway
Wichita, Kansas

FILE NO. _____

LOCATION NE-SE-SE

SEC. 18 TWP. 23 RGE 13W

Dry Hole ✓ Abandoned Oil Well _____ Abandoned Gas Well _____

I have this date completed supervision of plugging of:

Well No. 1 Lease French

Operator Quick Drilling, Inc. Address Box 331 St. John Kansas

Field _____ County Stafford

Total Depth 4000 Feet.

Plugging Contractor Quick Drilling Inc.

Plugging Contractor's License No. _____

Address Box 331 St. John Kansas

(Describe Briefly the manner in which the well was plugged)

Surf. Pipe 8 3/8 at 210 c.w.c. - lost 30 feet of surf pipe - back to 180 feet - Plugged with hole full of Gell mud to 210 and solid plug 8 feet long sand 3/4 Hl of Rock on it - top of rock at 195 feet and 25 cu. of cement through drill pipe and Gell mud to 35 feet and 3 cu. of Hs, & Plug and 10 cu. of cement to base of cellar - 2 PM

R.M. Brouder
District Conservation Agent

Date Jan - 9 - 1957

PLUGGING
FILE SEC 18 T. 23 R. 13W
BOOK PAGE 133 LINE 1

RECEIVED
STATE CORPORATION COMMISSION
1-10-57

CONSERVATION DIVISION
Wichita, Kansas