DISTRICT CONSERVATION AGENT'S REPORT

TO:

State Corporation Commission Conservation Division

	A CONTRACTOR OF THE PARTY OF TH
. Salar de la constantina del constantina de la constantina del constantina de la co	sara.

conservation Division 211 North Broadway	FILE NO
Wichita, Kansas	LOCATION ITW-NW-NW
	SEC. 23 TWP.21 RGE. 16W
	· · · · · · · · · · · · · · · · · · ·
Dry HoleAbandoned Oil We	Abandoned Gas Well
I have this date completed supervision of	plugging of:
Well No. 1 Lease Lawton.	
Dperator <u>Leben Drilling Company.</u>	905 Central Bldg. Address Wichita, Kansas.
Field	County Pawnee.
Fotal Depth 3860:	
Plugging Contractor Leben Drilling Go	ompany.
Plugging Contractor's License No.	
Address 905 Central_Bldg. Wid	chita. Kansas.
(Describe Briefly the mann	er in which the well was plugged)
Surface pipe - 8 5/8" @ 986' c.w.	.c. 450 sx.
Jet up pits and circulate heavy r	mud. Then pulled pipe out and mud up
to 350' from top, k sx. hulls, p	lug, rock bridge and 20 sx. cem. through
drill pipe. Mud to 40' from top,	sx. hulls, plug and 10 sx. cem.
to base of cellar.	
د	Wilton Lake and.
	District Conservation Agent
	Date 7-17-57
	CIEDUS CONTRASCION
PLUGGI	VG JUL 191917 7-19-57
FILE SEC 23 T 2	1 RIGW " DWISION
BOOK PAGE 30 L	INE_2