KANSAS STATE CORPORATION COMMISSION

CONSERVATION DIVISION AGENT'S REPORT

TO:
Jewel M. Ogden, Director
500 Insurance Du 1ding
212 North Market
Wichita 2, Kansas



,	:			1	,	•
File No.	Cot	unty:	McPherson	<u> </u>	·	. . .
Location:	SW-SE-NE	Sec.	8 Twp.	2I Rge		(W)
Name of Field:	Graber	·	Total	Depth:	3460	
I have this date comp	leted supervisi	Lon of plugg	ing of:			
Lease Name:	Groeman		,	Well No	I	.·
Operator's Full Name:	Crowe Drilling	Co, Inc.	· .			· · · · · ·
Complete Address:	323 Board Trac	le Bldg, Wic	hita Kansas.			
Plugging Contractor:	Renfro Drillin	ng Vo.	· ·	\	A Page 1 Car	
Address:	316 Insurance	Bldg, Wichi	ta Kansas.	License N	o Rotary	
Oil WellGas	Well	_Input Well_	swd	Well_	D & AX	,
Other well as hereaft	er indicated:				*************************************	
Was any delay in plug	ging operations	caused by	Conservation	Division Ag	ent? Yes_	No X
If yes how long?	<u></u>	Rea	son:		· · · · · · · · · · · · · · · · · · ·	
	·		· · · · · · · · · · · · · · · · · · ·		(·
		· · · · · · · · · · · · · · · · · · ·		· 1	·	
Operation Completed:	Hour 5:PM	Day	26 <u>M</u> o	nth II	Ye.	ar_60
The above well was pl	ugged as follow	78:	•		· ·	
Filled hole w/ 36 Vis	mud from T.D.	3460' back	to I80' set 1	halco plug I	/2 sak hills	
and 20 Sax cement. Fi	.lled hole w/ 36	Vis mud fro	m I20° back	to 35' set ha	alco plug	
I/2 sak hulls and 8 s	sax cement. 8 5/	/8" surface	pipe 3' belo	w ground leve	el.	·
Rat hole plugged w/ 2	sax cement 3'	below groun	d_level.	1	· ·	
	· · · · · · · · · · · · · · · · · · ·			CEIVE		• •
				CEMPA COMM	SIUN	· · · · · · · · · · · · · · · · · · ·
		w = 1	•	DEC 6 Jean	12-6-6	60
				-RVATION D IVIS /ichita, Kansas	IOIY ;	,
		٠, , , , ,		· · · · · · · · · · · · · · · · · · ·	•	
		Sig	ned:	acilm	Jone	1
4	<i>^</i>		Co	nservation b	lyision Ager	nt .
Reviewed:	ekon.					
Field	d Supervisor					

A Day

Remarks:

INVOICED

INV. NO. 3645-E